

Cube Parts from McMaster Carr		
McMaster Part Number and link	Description	# required per Cube
https://www.mcmaster.com/2733A831	Cobalt Steel Round-Shank Reamer 22 wire ga	Only one needed until worn
https://www.mcmaster.com/9714K65	Wave Disc Spring, 1.051" ID, 1.351" OD, 0.015" Thick	1
https://www.mcmaster.com/92125A238	18-8 Stainless Steel Hex Drive Flat Head Screw, M6 x 1 mm Thread, 16 mm Long	1
https://www.mcmaster.com/98541A119	External Retaining Ring for 12 mm OD, Black-Phosphate 1060-1090 Spring Steel	1
https://www.mcmaster.com/92000A118	Passivated 18-8 Stainless Steel Pan Head Phillips Screws, M3 x 0.5mm Thread, 8mm Long	3
https://www.mcmaster.com/93475A210	18-8 Stainless Steel Washer for M3 Screw Size, 3.2 mm ID, 7 mm OD	3
https://www.mcmaster.com/96001A264	Torx Rounded Head Thread-Forming Screws for Plastic, 18-8 Stainless Steel, Number 6 Size, 1/2" Long	4
https://www.mcmaster.com/96001A156	Torx Rounded Head Thread-Forming Screws for Plastic, 18-8 Stainless Steel, Number 2 Size, 3/8" Long	6
https://www.mcmaster.com/96001A268	Torx Rounded Head Thread-Forming Screws for Plastic, 18-8 Stainless Steel, Number 6 Size, 3/4" Long	6
https://www.mcmaster.com/96710A215	Stainless Steel Pan Head Torx Screws, 4-40 Thread Size, 1/4" Long	1
https://www.mcmaster.com/91841A005	18-8 Stainless Steel Hex Nut, 4-40 Thread Size	1